

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Condition
1	BRS	242	(select\$ and plurality same threshold and power and supply).clm.	USPAT ; US-PG PUB	2002/06/15 12:13		Truncation overflow. 1
2	BRS	14	((select\$ and plurality same threshold and power and supply).clm.) and 324/\$.ccls.	USPAT ; US-PG PUB	2002/04/04 16:30		0
3	BRS	3	("5220216" "5684423" "5821783").PN.	USPAT	2002/04/04 16:36		0
4	BRS	0	6157222.URPN.	USPAT	2002/04/04 16:39		0
5	BRS	0	6157222.URPN.	USPAT	2002/04/04 16:39		0
6	BRS	18	((select\$ and plurality same threshold and power and supply).clm.) and 326/\$.ccls.	USPAT ; US-PG PUB	2002/04/04 16:50		0
7	BRS	2	((select\$ and plurality same threshold and power and supply).clm.) and 326/\$.ccls.) and programmable	USPAT ; US-PG PUB	2002/04/04 16:46		0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error for this entry
8	BRS	39	((select\$ and plurality same threshold and power and supply).clm.) and 327/\$.ccls.	USPAT ; US-PG PUB	2002/04/04 16:50		0
9	BRS	5	((select\$ and plurality same threshold and power and supply).clm.) and 327/\$.ccls. and programmable	USPAT ; US-PG PUB	2002/04/04 16:50		0
10	BRS	4	5781043.URPN.	USPAT	2002/04/04 16:54		0
11	BRS	4	5781043.URPN.	USPAT	2002/04/04 17:00		0
12	BRS	1	5894423.URPN.	USPAT	2002/04/04 17:01		0
13	BRS	6	("5382839" "5420798" "5444663" "5497112" "5675272" "5781043").PN.	USPAT	2002/04/04 17:02		0
14	BRS	6	5444663.URPN.	USPAT	2002/04/04 17:32		0
15	BRS	6	5444663.URPN.	USPAT	2002/04/04 17:36		0
16	BRS	3	("4585955" "4806789" "5046052").PN.	USPAT	2002/04/04 17:36		0
17	BRS	0	6157222.URPN.	USPAT	2002/04/20 20:29		0
18	BRS	3	("5220216" "5684423" "5821783").PN.	USPAT	2002/04/20 20:29		0
19	BRS	448	324/74.ccls.	USPAT ; US-PG PUB	2002/04/20 20:36		0
20	BRS	1	324/74.ccls. and selectable near threshold	USPAT ; US-PG PUB	2002/04/20 20:37		0
21	BRS	0	326/50.ccls. and selectable near threshold	USPAT ; US-PG PUB	2002/04/20 20:38		0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error for this entry
31	BRS	27	(power adj supply same increased same above decreased same below and select).clm.	USPAT ; US-PG PUB	2002/04/20 21:09		0
32	BRS	134	(power adj supply same increased same above decreased same below and threshold).clm.	USPAT ; US-PG PUB	2002/04/20 21:11		0
33	BRS	16	(power adj supply same increased same above decreased same below and threshold and select).clm.	USPAT ; US-PG PUB	2002/04/20 21:13		0
34	BRS	2	(threshold and power and supply and select and switch and follow).clm.	USPAT ; US-PG PUB	2002/04/20 21:15		0
35	BRS	8	(threshold and power and supply and select and switch adj circuit).clm.	USPAT ; US-PG PUB	2002/04/20 21:19		0
36	BRS	99	(select\$ near threshold and power and supply).clm.	USPAT ; US-PG PUB	2002/04/20 21:20	Truncation overflow.	1

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Errors
37	BRS	0	6157222.URPN.	USPAT	2002/04/20 21:28		0
38	BRS	3	("5220216" "5684423" "5821783").PN.	USPAT	2002/04/20 21:28		0
39	BRS	1	(selectable near threshold).ti.	USPAT ; US-PG PUB	2002/04/20 21:46		0
40	BRS	3	(selectable near2 threshold).ti.	USPAT ; US-PG PUB	2002/04/20 21:43		0
41	BRS	25	(voltage adj detector adj including voltage near following and power adj supply and selectable near threshold).clm.	USPAT ; US-PG PUB	2002/04/20 21:44		0
42	BRS	780	voltage near regulator and threshold and follower	USPAT ; US-PG PUB	2002/05/08 14:34		0
43	BRS	260	voltage near regulator and threshold and voltage near follower	USPAT ; US-PG PUB	2002/05/08 14:35		0
44	BRS	157	voltage near regulator and threshold and voltage near follower and detector	USPAT ; US-PG PUB	2002/05/08 15:19		0
45	BRS	99	(voltage near detector).ti.	USPAT ; US-PG PUB	2002/05/08 14:45		0
46	BRS	0	(voltage near regulator and threshold and voltage near follower and detector) and ((voltage near detector).ti.)	USPAT ; US-PG PUB	2002/05/08 14:37		0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Disposition
47	BRS	99	((voltage near detector).ti.) not (voltage near regulator and threshold and voltage near follower and detector)	USPAT ; US-PG PUB	2002/05/08 14:38		0
48	BRS	42	((voltage near detector).ti.) and threshold	USPAT ; US-PG PUB	2002/05/08 14:39		0
49	BRS	4	((voltage near detector).ti.) and threshold and follower	USPAT ; US-PG PUB	2002/05/08 14:39		0
50	BRS	2	((voltage near detector).ti.) and follower and switch	USPAT ; US-PG PUB	2002/05/08 14:46		0
51	BRS	32	(voltage near regulator and threshold and voltage near follower and detector) and switch near circuit	USPAT ; US-PG PUB	2002/05/08 14:52		0
52	BRS	0	voltage near follwer and switch near circuit and threshold near select\$ and detector	USPAT ; US-PG PUB	2002/05/08 14:53	Truncation overflow.	1

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Position
53	BRS	46625	select\$ same threshold	USPAT ; US-PG PUB	2002/05/08 14:55	Truncation overflow.	1
54	BRS	9567	select\$ with threshold and detector	USPAT ; US-PG PUB	2002/05/08 14:56	Truncation overflow.	1

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Position
55	BRS	162	(select\$ with threshold and detector) and voltage near follower	USPAT ; US-PG PUB	2002/05/08 14:57		0
56	BRS	4305	select\$ near2 threshold and detector	USPAT ; US-PG PUB	2002/05/08 14:56	Truncation overflow.	1
57	BRS	57	(select\$ near2 threshold and detector) and voltage near follower	USPAT ; US-PG PUB	2002/05/08 14:57		0
58	BRS	14	5132565.URPN.	USPAT	2002/05/08 15:04		0
59	BRS	9	("4125788" "4194135" "4456838" "4476426" "4728821" "4801824" "4818901" "4833342" "5021691").PN.	USPAT	2002/05/08 15:14		0
60	BRS	77	(voltage near regulator and threshold and voltage near follower and detector) and memory	USPAT ; US-PG PUB	2002/05/08 15:20		0

	Type	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	E r r o r s	E r r o r s
61	BRS	44	(voltage near regulator and threshold and voltage near follower and detector) and memory and processor	USPAT ; US-PG PUB	2002/05/08 15:20			0
62	BRS	462	rapp.in.	USPAT ; US-PG PUB	2002/05/08 15:33			0
63	BRS	61	rapp.in. and karl	USPAT ; US-PG PUB	2002/05/08 15:33			0
64	BRS	61	rapp.in. and karl	USPAT ; US-PG PUB	2002/05/08 15:33			0
65	BRS	103	324/771.ccls.	USPAT ; US-PG PUB	2002/05/08 16:55			0
66	BRS	2	324/771.ccls. and voltage near follower	USPAT ; US-PG PUB	2002/05/08 16:55			0
67	BRS	29	324/771.ccls. and threshold	USPAT ; US-PG PUB	2002/05/08 16:56			0
68	BRS	0	5748548.URPN.	USPAT	2002/05/08 17:06			0
69	BRS	10	("4365316" "4560937" "4794564" "4975883" "5083045" "5109187" "5199032" "5426616" "5426626" "5583820").PN.	USPAT	2002/05/08 17:06			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Errors
70	BRS	9	("4683382" "4975883" "5193198" "5301161" "5305275" "5331599" "5339272" "5412331" "5414669").PN.	USPAT	2002/05/08 17:15		0
71	BRS	6	("4446534" "4916389" "4994688" "5086238" "5179539" "5254880").PN.	USPAT	2002/05/08 17:21		0
72	BRS	3	("4433390" "4712195" "4777626").PN.	USPAT	2002/05/08 17:27		0
73	BRS	31	4975883.URPN.	USPAT	2002/05/08 17:28		0
74	BRS	32	5426616.URPN.	USPAT	2002/05/08 17:31		0
75	BRS	1292	365/226.ccls.	USPAT ; US-PG PUB	2002/05/08 17:36		0
76	BRS	10	365/226.ccls. and voltage near follower and threshold	USPAT ; US-PG PUB	2002/05/08 17:37		0
77	BRS	12	365/226.ccls. and voltage near follower	USPAT ; US-PG PUB	2002/05/08 17:42		0
78	BRS	8	365/226.ccls. and voltage near follower and switch and threshold	USPAT ; US-PG PUB	2002/05/08 17:42		0
79	IS&R	3	((("5132565") or ("6157222") or ("5220216"))).PN.	USPAT ; US-PG PUB	2002/06/15 12:13		0